

Inspection Photos
Location Name: LORECITO 2-7
API #: 05-071-08140
Insp. Doc. # 695100164



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN/METER HOUSE

Inspection Photos
Location Name: LORECITO 2-7
API #: 05-071-08140
Insp. Doc. # 695100164



Colorado Oil & Gas Conservation Commission
37.10465, -104.8193, 2172.0m, 202°
2019/02/11 12:52:34



Colorado Oil & Gas Conservation Commission
37.00454, -104.4903, 51°
2019/02/11 12:52:48

PHOTO 3: STAINED SOIL UNDER GEAR BOX ON PUMP JACK SKID.

PHOTO 4: UNUSED EQUIPMENT STORED ON LOCATION

Inspection Photos
Location Name: LORECITO 2-7
API #: 05-071-08140
Insp. Doc. # 695100164



PHOTO 5: PRODUCED WATER APPEARS TO BE ABOVE THE 2' FREEBOARD REQUIREMENT. FREEBOARD MARKER IS NOT INSTALLED ON LOWEST ELEVATION OF PIT.

PHOTO 4: UNUSED EQUIPMENT STORED ON LOCATION

