

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/11/2019

Submitted Date:

02/12/2019

Document Number:

690101084

FIELD INSPECTION FORM

Loc ID 439204 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10459
Name of Operator: EXTRACTION OIL & GAS INC
Address: 370 17TH STREET SUITE 5300
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Rickard, Jeff		jrickard@extractionog.com	
Leonard, Mike		mike.leonard@state.co.us	
		COGCCInspections@extracti onog.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co. us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
439205	WELL	PR	02/01/2016	LO	123-40351	Waag 19	EG

General Comment:

COGCC engineering integrity inspection in response to COGCC form 22 accident report #401933418 filed by Extraction Oil and Gas on 02/11/2019. Details of observations made are located in the comment section of report.

Inspected FacilitiesFacility ID: 439205 Type: WELL API Number: 123-40351 Status: PR Insp. Status: EG**COGCC Comments**

Comment	User	Date
<p>As outlined by Extraction Oil and Gas on COGCC Form 22 received on 02/11/2019 (accident tracking #401933418): A fire occurred on a Separator on the Waag South pad at Approx. 9:00 Am on 2/8/19. The fire was controlled shortly thereafter and limited to the primary containment. No injuries occurred. The cause at this time is still under investigation, a root cause and necessary reports will be submitted with the Supplemental Accident Report.</p>	maclarej	02/12/2019
<p>EG Integrity inspection in response to incident. COGCC Inspector met with Extraction Oil and Gas construction foreman Julian Munoz on location. A fire occurred on a heated horizontal separator associated with the Waag 19 C well; the fire appears to have started/ been present at the North end of the equipment and in the area of fire tube assembly. The fire also impacted the Waag 20N heated horizontal separator (adjacent to and east of the Waag 19 C equipment). Extraction oil and gas contract crews are in the process of removing both separators at this time. Inspections of all equipment in the area is being scheduled by the operator. Extraction is in the process of investigating the root cause of failure leading to the fire. No injuries reported.</p>	maclarej	02/12/2019
<p>Note: A COGCC form 44 is required for Grade 1 gas leaks (see COGCC rule 1104.k Gas Leak Reporting)</p>	maclarej	02/12/2019