

# Interim Reclamation and Stormwater Inspection

February 11, 2019

Operator: ENERPLUS RESOURCES (USA) CORPORATION - #10177

Location ID: 449968

Inspection Document #: 682404503

Weld County, CO

SWSW Section 28 T8N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Colorado Lakes /Pad  
Location ID: 449968



**Photo 1.** Photo taken from the north eastern topsoil stockpile on 12/14/2018, facing South. Operator has failed to prevent weed establishment on the topsoil stockpile. Note: Appears the Operator attempted to seed the topsoil with desirable vegetation (e.g., blue grama) but weedy, annual vegetation (Kochia) was observed throughout most of the stockpile.



**Photo 2.** Photo taken from the north eastern topsoil stockpile on 2/11/19, facing South. Operator has mowed the weeds from the topsoil stockpiles and other portions of the location. Ongoing weed management and monitoring is required, and needs to occur in accordance to COGCC rules and regulations.



Inspection Photos  
Location Name: Colorado Lakes /Pad  
Location ID: 449968



**Photo 3.** Photo taken from the north eastern topsoil stockpile on 12/14/2018, facing Northeast. Silt fence BMP in need of maintenance.



**Photo 4.** Photo taken from the northeastern location on 2/11/19, facing Northeast. Appears the Operator has made repairs to the silt fence that were previously observed; however, BMP is in need of maintenance.



Inspection Photos  
Location Name: Colorado Lakes /Pad  
Location ID: 449968



**Photo 5.** Photo taken along the access road just beyond the entrance of the location on 12/14/2018, facing South. Gully erosion has formed along a section of the access road.



**Photo 6.** Photo taken along the access road just beyond the entrance of the location on 2/11/19, facing South. Operator has made repairs but has failed to install additional BMPs. It is not sufficient to only make repairs.