

Inspection Photo (s)
Specialty 12D
API # 05-045-18649
Inspection # 689303242



Location Photo #1



Location Photo #2

Inspection Photo (s)
Specialty 12D
API # 05-045-18649
Inspection # 689303242



Location Photo #3



Location Photo #4, Stained material in South West corner of battery containment.

Inspection Photo (s)
Specialty 12D
API # 05-045-18649
Inspection # 689303242



**Location Photo #5, Stained material around
load out basins.**

