

Inspection Photos
Operator Name: Mustang Resources
LLC
Location ID: 461615



**Sales Flowline was rerouted and pressured
tested**

Inspection Photos
Operator Name: Mustang Resources
LLC
Location ID: 461615



Source of release



4 Holes on top of flowline

Inspection Photos
Operator Name: Mustang Resources
LLC
Location ID: 461615



Open exaction hole



Additional abandoned/unclaimed 2" and 8" pipelines were also capped/removed.

Inspection Photos
Operator Name: Mustang Resources
LLC
Location ID: 461615



**Mustang Recourses flowline plugged
abandoned**