

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/13/2019

Submitted Date:

02/14/2019

Document Number:

682600623**FIELD INSPECTION FORM**
 Loc ID 321668 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 51065Name of Operator: LOEB LLC\* HERMAN LAddress: P O BOX 838City: LAWRENCEVILLE State: IL Zip: 62439**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Middagh, Jesse	815-556-0756	jesse@loeboil.com	
Sutphin, Dirk		dirk.sutphin@state.co.us	
Pelton, Shane	620-617-5870	shane@loeboil.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207725	WELL	PR	07/31/1998	OW	017-06660	WHITE 'AL' 1	EI

**General Comment:**

This is a follow up inspection to COGCC Inspection # 682600610 which found the wellhead to be venting gas and invalid operator contact information posted on the lease sign. At the time of this inspection on 2/19/2019 both issues have been corrected and the well is no longer venting gas.

**Inspected Facilities**Facility ID: 207725 Type: WELL API Number: 017-06660 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682600633	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4734686">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4734686</a>