

Inspection Photos
Operator Name: Laramie Energy LLC
Location ID: 461292



Pipeline leak discovered at the surface

Inspection Photos
Operator Name: Laramie Energy LLC
Location ID: 461292



Source of release



Repaired Flowline

Inspection Photos
Operator Name: Laramie Energy LLC
Location ID: 461292



External View of Pipe Corrosion