

Interim Reclamation and Stormwater Inspection

February 1, 2018

Operator: BURLINGTON RESOURCES OIL & GAS LP – 26580

Location ID: 453244

Inspection Document #: 674902469

Adams County, CO

SWSE Section 27 T4S R65W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP/4S65W27

Location ID: 453244



Photo 1. Photo taken from the southern perimeter of the location, facing West. Appears the Operator has performed interim reclamation activities to reduce disturbance areas only needed for production operations at the location, with the evidence of drilling rows and straw crimped mulch.



Photo 2. Photo taken from the location, facing South. See comments from Photo 1.

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP/4S65W27

Location ID: 453244



Photo 3. Photo taken from the location, facing Northeast. See comments from Photo 1.



Photo 4. Photo taken from the location, facing West. See comments from Photo 1.

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP/4S65W27

Location ID: 453244



Photo 5. Photo taken from the location, facing Northeast. At the time of this inspection, it appears the Operator has not installed sufficient stormwater and erosion control BMPs in accordance to Rule 1002.f. standards. Photo depicts erosion observed on location.



Photo 6. Photo taken from the northern perimeter of the location, facing West. See comments from Photo 1.

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP/4S65W27

Location ID: 453244



Photo 7. Photo taken from the northern perimeter of the location, facing West. See comments from Photo 1.



Photo 8. Photo taken from the location, facing Northeast. See comments from Photo 1.

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP/4S65W27

Location ID: 453244



Photo 9. Photo taken from the southern perimeter of the location, facing Northeast. This location has a poor design for implementing Interim Reclamation and not in compliance with Rule 1002.e.(1).



Photo 10. Photo taken from the southern perimeter of the location, facing East. See comments from Photo 9.