

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/14/2019

Submitted Date:

02/15/2019

Document Number:

675001942**FIELD INSPECTION FORM**Loc ID 312498 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments3 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Graves, Jim		mrinc20@qwestoffice.net	
,		aak2@kahnjeeholding.com	<a href="#">All Inspections</a>
Ried, Jordan	970-563-400	maralextechjr@gmail.com	<a href="#">All Inspections</a>
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	<a href="#">Petroleum Engineer</a>
Fischer, Alex		alex.fischer@state.co.us	
, DNR		dnr_cogccengineering@state.co.us	<a href="#">All Engineering</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221784	WELL	SI	01/08/1992	GW	077-08386	DOMA ALBERTSON 1-32	TA

**General Comment:**

This is a follow up field inspection to inspection 689401608 dated 9/14/2018, any corrective actions not addressed from previous inspections are still applicable. This well is not listed on AOC 1V-609

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911 / 970-858-8550			
Corrective Action:				Date:
<b>Good Housekeeping:</b>				
Type	DEBRIS			
Comment:	Vegetation around wellhead.			
Corrective Action:	Comply with Rule 603.f .			Date: 11/15/2018
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	PIT			
Comment:				
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Deadman # & Marked	# 3			corrective date
Comment:	Only remains on location is a wellhead, empty pit with fence around it and 3 marked deadman			
Corrective Action:				Date:
<b>Venting:</b>				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:



**Inspected Facilities**Facility ID: 221784 Type: WELL API Number: 077-08386 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: MIT on 1/28/14. No Form 4 on file for continued TA status.Corrective Action: A Sundry Notice, Form 4, shall be submitted annually stating the method the well is closed to the atmosphere and plans for future operation.Date: 11/15/2018

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				

Comment: [Stormwater erosion appears to be controlled on the location at this time.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
Reference Point: _____	Other: _____	Length: _____	Width: _____	

**Lining:**

Liner Type:

Liner Condition:

Comment: [No facility ID or permit on file for pit. Corrective action from previous inspection still applicable.](#)Date: 11/25/2016

Corrective Action

Submit an eForm 15 Pit Report to update COGCC records with current information to comply with rule 903.a.  
 Date: 11/25/2016  
 Pits: NO SURFACE INDICATION OF PIT  
 Reclamation - Storm Water - Pit  
 Document Num Description URL  
 401763412 INSPECTION  
 SUBMITTED  
<http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4579218>  
 689401608 INSPECTION APPROVED  
<http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4584760>  
 689401609 Dome Albertson 1-32  
 Photos  
<http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4579211>  
 Attached

**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date:

**COGCC Comments**

Comment	User	Date
<a href="#">Only remains on location is a wellhead, empty pit with fence around it and 3 marked deadman</a>	wentzeld	02/14/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675001943	Inspection 675001942 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4735984">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4735984</a>

--