

Inspection Photos
Location Name: CHURCH 2
Location ID: 05-103-05331
Inspection: 679703019



Photo 1. Location looking south.



Inspection Photos
Location Name: CHURCH 2
Location ID: 05-103-05331
Inspection: 679703019



Photo 2. Weeds next to pump jack.



Photo 3. Weeds next to pump during inspection 679701727.



Inspection Photos
Location Name: CHURCH 2
Location ID: 05-103-05331
Inspection: 679703019



Photo 4. Trash on loading road below tank battery.



Photo 5. Trash on loading road below tank battery during inspection 67901727.

Inspection Photos
Location Name: CHURCH 2
Location ID: 05-103-05331
Inspection: 679703019



Photo 6. Insufficient berm capacity due to short berm on north side.




Photo 7. Insufficient berm capacity due to short berm on north side during inspection 679701727.