

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/14/2019

Submitted Date:

02/16/2019

Document Number:

688303823**FIELD INSPECTION FORM**Loc ID 317092 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 14855Name of Operator: CENTRAL OPERATING INCAddress: 1600 BROADWAY STE 1050City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Potter, Gail		centraloperatinginc@gmail.com	Office manager
Quintana, Laney	(303) 894-9576	centraloperatinginc@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236129	WELL	PR	12/01/2018	OW	121-08619	MARICK A-2	PR

General Comment:

Reinspection. Stained soil at wellhead and erosion near SE cor of south pit not repaired.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:	stuffing box leak		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	02/14/2019

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	236129	Type:	WELL	API Number:	121-08619	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR. Dec 2018 production reported to COGCC database.								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					

Comment: [Install or repair required BMPs per Rule 1002.f.](#)Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 01/15/2019

Pits: ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688303850	Central Operating Marick A-2 well sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4737270
688303851	Central Operating Marick A-2 wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4737271
688303852	Central Operating Marick A-2 pit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4737272