

Inspection Photos 2/06/19 and 2/08/19
Well: BULTHAUP 39-6
API # 05-123-26884



Anadarko signage at wellhead.



View of (TA) wellhead; flowline has been disconnected.

Inspection Photos 2/06/19 and 2/08/19
Well: BULTHAUP 39-6
API # 05-123-26884



Bulthaup 16-6 and 39-6 flowlines exposed in excavation; The 39-6 flowline (failed) is furthest right. Flowlines enter 4" casing pipe under marshy area. View south to wellheads.

Closer view of the 2" FBE CS flowlines and 1" HDPE gas supply/ return flowlines entering the 4" steel casing pipes

