

**Inspection Photo (s)**  
**Clough RMV 26-21**  
**API # 05-045-06976**  
**Inspection # 689303285**



**Location Photo #1**



**Location Photo #2, Rilling occurring along access road.**

**Inspection Photo (s)**  
**Clough RMV 26-21**  
**API # 05-045-06976**  
**Inspection # 689303285**



**Location Photo #3, Rilling occurring along access road.**



**Location Photo #4, Rilling occurring along access road.**

**Inspection Photo (s)**  
**Clough RMV 26-21**  
**API # 05-045-06976**  
**Inspection # 689303285**



**Location Photo #5, Rilling occurring along access road.**



**Location Photo #6, Rilling occurring along access road.**

**Inspection Photo (s)  
Clough RMV 26-21  
API # 05-045-06976  
Inspection # 689303285**



**Location Photo #7, Rilling occurring along access road.**



**Location Photo #8, Rilling occurring along access road.**

**Inspection Photo (s)  
Clough RMV 26-21  
API # 05-045-06976  
Inspection # 689303285**



**Location Photo #9, Rilling occurring along access road.**



**Location Photo #10, Sediment being moved across road.**

**Inspection Photo (s)  
Clough RMV 26-21  
API # 05-045-06976  
Inspection # 689303285**



**Location Photo #11, Sediment being moved across road.**



**Location Photo #12, Sediment is being carried into vegetation.**