

Inspection Photo (s)
Clough 128
API # 05-045-06384
Inspection # 689303297



Location Photo #1



Location Photo #2, Unmarked dead man anchor.

Inspection Photo (s)
Clough 128
API # 05-045-06384
Inspection # 689303297



**Location Photo #3, Unmarked/unused flow
line riser.**