

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/19/2019

Submitted Date:

02/19/2019

Document Number:

689303273**FIELD INSPECTION FORM**
 Loc ID 335321 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Rider, Lindsay	970-285-2711	cogcc.inspections@caerusoila ndgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266772	WELL	PR	10/09/2003	GW	045-09181	ALP 25-9C (J25)	PR
266773	WELL	PR	10/09/2003	GW	045-09180	ALP 25-16 (J25)	PR
266774	WELL	PR	11/01/2012	GW	045-09179	ALP 25-8C (J25)	PR
266796	WELL	PR	10/12/2003	GW	045-09184	ALP 25-10 (J25)	PR
266797	WELL	PR	06/11/2004	GW	045-09183	ALP 25-9 (J25)	PR
281899	WELL	PR	05/27/2006	GW	045-11567	ALP 25-9D(J25NW)	PR
281901	WELL	PR	05/27/2006	GW	045-11568	ALP 25-8CI (J25NW)	PR

General Comment:

This is a follow up inspection from [Doc# 689302643](#) and [689302952](#). Required Corrective Action (s) items noted in previous inspections have been satisfied.

Equipment inventory has not changed on location.

Inspected Facilities									
Facility ID:	266772	Type:	WELL	API Number:	045-09181	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	266773	Type:	WELL	API Number:	045-09180	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	266774	Type:	WELL	API Number:	045-09179	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	266796	Type:	WELL	API Number:	045-09184	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	266797	Type:	WELL	API Number:	045-09183	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	281899	Type:	WELL	API Number:	045-11567	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	281901	Type:	WELL	API Number:	045-11568	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303274	Inspection photo 689303274	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4740717