

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/01/2019

Submitted Date:

02/21/2019

Document Number:

688000266**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 88370Name of Operator: TIMKA RESOURCES LTDAddress: 2116 EAST HIGHWAY 402City: LOVELAND State: CO Zip: 80537**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pivonka, Todd	(970) 667-9861	timkaresources@hotmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
117729	PIT	AC			-	THEURER FARMS 22-28	EI
117730	PIT	AC			-	THEURER FARMS 22-28	EI
119604	PIT	AC			-	THEURER FARNS 22-28	EI

General Comment:

Environmental inspection related to planned closure of former oil skim pit (117729) and produced water pit (117730) and pit facility ID 119604 (no documents).

Inspected Facilities								
Facility ID:	117729	Type:	PIT	API Number: -	Status:	AC	Insp. Status:	EI
Facility ID:	117730	Type:	PIT	API Number: -	Status:	AC	Insp. Status:	EI
Facility ID:	119604	Type:	PIT	API Number: -	Status:	AC	Insp. Status:	EI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 117730Lat: 40.199441Long: -103.207691

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type:

Liner Condition:

Comment:

Produced water pit is currently not being used due to produced water being injected into Theurer 1-B injection well. Operator discussed closing the pit during inspection.

Corrective Action

Submit an eForm 27 for the closure of the produced water pit.

Date: 03/22/2019**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date: _____

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date: _____

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date: _____

Type: Skimming/SettlingLined: NOPit ID: 117729Lat: 40.199365Long: -103.208145

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type:

Liner Condition:

Comment:

COGCC met operator on site and discussed soil sampling locations. A Form 27 is needed to track this remediation project.

Corrective Action

Submit an eForm 27 with the soil sample analytical results.

Date: 03/22/2019**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date: _____

Netting:

Netting Type:	Netting Condition:	
Comment:		
Corrective Action		Date:
Anchor Trench Present:	Oil Accumulation:	2+ feet Freeboard:
Comment:		
Corrective Action		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688000267	Location photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4741411