

Inspection Photos

API: 05-071-06559

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 2/14/2019

Inspection Photos



Photo 1. Facing northwest along the access road.

Inspection Photos



Photo 2. Facing northwest along the access road.

Inspection Photos



Photo 3. Facing northwest toward the location.

Inspection Photos



Photo 4. Facing southeast toward the location.

Inspection Photos



Photo 5. Facing southeast toward the cutslope.

Inspection Photos



Photo 6. Facing southeast toward the fillslope.

Inspection Photos



Photo 7. Facing northwest toward the recontoured fill slope.