

Inspection Photos

API: 05-071-09411

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 2/14/2019

Inspection Photos



Photo 1. Facing east at the location. Interim vegetation appears to be established.

Inspection Photos



Photo 2. Facing south toward the well.

Inspection Photos



Photo 3. Facing toward the pit. The 2ft. Freeboard marker is present.