

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/22/2019

Submitted Date:

02/22/2019

Document Number:

689303321

**FIELD INSPECTION FORM**

Loc ID 311615 Inspector Name: Holtz, Darin On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

9 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Rider, Lindsay	970-285-2711	cogcc.inspections@caerusoila ndgas.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269700	WELL	PR	03/15/2004	GW	045-09399	SHIDELER 19-6D(F19)	PR
270078	WELL	PR	09/11/2004	GW	045-09451	HMU 19-2B (F19)	PR
270079	WELL	PR	03/15/2004	GW	045-09452	SHIDELER 19-7B (F19)	PR
270291	WELL	PR	11/29/2004	GW	045-09519	SHIDELER 19-6B (F19)	PR
270713	WELL	PR	09/16/2004	GW	045-09789	HMU 19-4D (F19)	PR
270714	WELL	PR	09/15/2004	GW	045-09788	HMU 19-3B (F19)	PR

**General Comment:**

This is a follow up inspection from Doc# 689302942. Required Corrective Action (s) items noted in previous inspections have been satisfied.  
Holes in battery liner and unmarked/unused flowline was removed.  
Equipment inventory has not changed on location.

Inspected Facilities									
Facility ID:	<u>269700</u>	Type:	<u>WELL</u>	API Number:	<u>045-09399</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:						Date:			
Facility ID:	<u>270078</u>	Type:	<u>WELL</u>	API Number:	<u>045-09451</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:						Date:			
Facility ID:	<u>270079</u>	Type:	<u>WELL</u>	API Number:	<u>045-09452</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:						Date:			
Facility ID:	<u>270291</u>	Type:	<u>WELL</u>	API Number:	<u>045-09519</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:						Date:			
Facility ID:	<u>270713</u>	Type:	<u>WELL</u>	API Number:	<u>045-09789</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:						Date:			
Facility ID:	<u>270714</u>	Type:	<u>WELL</u>	API Number:	<u>045-09788</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303322	Inspection photo 689303322	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4743314">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4743314</a>