

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/22/2019

Submitted Date:

02/22/2019

Document Number:

689303327

FIELD INSPECTION FORM

Loc ID 334575 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Rider, Lindsay	970-285-2711	cogcc.inspections@caerusoila ndgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268669	WELL	PR	07/09/2004	GW	045-09283	ROSE RANCH 10-15B (B15W)	PR
268672	WELL	PR	05/28/2004	GW	045-09282	ROSE RANCH 10-16C1 (B15W)	PR
268673	WELL	PR	06/11/2004	GW	045-09281	ROSE RANCH 10-15C (B15W)	PR
268674	WELL	PR	11/30/2006	GW	045-09280	ROSE RANCH 10-15A (B15W)	PR

General Comment:

This is a follow up inspection from Doc# 689302930. Required Corrective Action (s) items noted in previous inspections have been satisfied.
Unused equipment was removed.
Equipment inventory has not changed on location.

Inspected Facilities

Facility ID: 268669 Type: WELL API Number: 045-09283 Status: PR Insp. Status: PR

Producing Well

Comment: [Well Producing on plunger lift.](#)

Corrective Action:

Date:

Facility ID: 268672 Type: WELL API Number: 045-09282 Status: PR Insp. Status: PR

Producing Well

Comment: [Well Producing on plunger lift.](#)

Corrective Action:

Date:

Facility ID: 268673 Type: WELL API Number: 045-09281 Status: PR Insp. Status: PR

Producing Well

Comment: [Well Producing on plunger lift.](#)

Corrective Action:

Date:

Facility ID: 268674 Type: WELL API Number: 045-09280 Status: PR Insp. Status: PR

Producing Well

Comment: [Well Producing on plunger lift.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303329	Inspection photo 689303329	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4743317