

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/14/2019

Submitted Date:

02/16/2019

Document Number:

688303823

FIELD INSPECTION FORM

Loc ID 317092 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 14855
Name of Operator: CENTRAL OPERATING INC
Address: 1600 BROADWAY STE 1050
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Potter, Gail		centraloperatinginc@gmail.com	Office manager
Quintana, Laney	(303) 894-9576	centraloperatinginc@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236129	WELL	PR	12/01/2018	OW	121-08619	MARICK A-2	PR

General Comment:

Reinspection. Stained soil at wellhead and erosion near SE cor of south pit not repaired.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:	stuffing box leak		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: <u>02/14/2019</u>

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 236129 Type: WELL API Number: 121-08619 Status: PR Insp. Status: PR

Producing Well

Comment: [PR. Dec 2018 production reported to COGCC database.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					

Comment: [Install or repair required BMPs per Rule 1002.f.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 01/15/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401942720	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4737284
688303850	Central Operating Marick A-2 well sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4737270
688303851	Central Operating Marick A-2 wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4737271
688303852	Central Operating Marick A-2 pit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4737272