

# Construction and Storm Water Inspection

February 20, 2019

Operator: CRESTONE PEAK RESOURCES OPERATING LLC – 10633

Location ID: 451044

Inspection Document #: 674902526

Weld County, CO

NWNE Section 19 T2N R68W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: CRESTONE PEAK RESOURCES OPERATING LLC – 10633/2N68W19

Location ID: 451044



**Photo 1.** Photo taken from the access road near the entrance of the location off CR 20.5, facing South. Operator has installed a track pad and gravel potentially to limit tracking onto the county road.



**Photo 2.** Photo taken from the entrance of the location off CR 20.5, facing North. See comments from Photo 1.



## Inspection Photos

Location Name: CRESTONE PEAK RESOURCES OPERATING LLC – 10633/2N68W19

Location ID: 451044



**Photo 3.** Photo taken from eastern perimeter of the location, facing Southeast. Appears the Operator is installing sediment traps with stabilized outlets around the original permitted location.



**Photo 4.** Photo taken from northeastern perimeter of the location, facing South. Photo illustrates the ditch and berm BMP that has been installed around the perimeter of the location.



## Inspection Photos

Location Name: CRESTONE PEAK RESOURCES OPERATING LLC – 10633/2N68W19

Location ID: 451044



**Photo 5.** Photo taken from northeastern perimeter of the location, facing South. Photo illustrates the ditch and berm BMP that has been installed around the perimeter of the location. Parts of the BMP remain unconsolidated.



**Photo 6.** Photo taken from northwestern perimeter of the unpermitted disturbance area, facing South. Photo illustrates the ditch and berm BMP that has been installed around the perimeter of the location has been tracked through by equipment and opens to adjacent field with no stormwater BMP perimeter.



## Inspection Photos

Location Name: CRESTONE PEAK RESOURCES OPERATING LLC – 10633/2N68W19

Location ID: 451044



**Photo 7.** Photo taken from western perimeter of the location, facing South. Appears flowline ROW construction is underway. Parts of the ditch and berm BMP remain unconsolidated.



**Photo 8.** Photo taken from western perimeter of the flowline ROW, facing Southwest. See comments from Photo 7.



## Inspection Photos

Location Name: CRESTONE PEAK RESOURCES OPERATING LLC – 10633/2N68W19

Location ID: 451044



**Photo 9.** Photo taken from western perimeter of the flowline ROW, facing Northeast. See comments from Photo 7.



**Photo 10.** Photo taken from southern perimeter of the location looking towards the flowline ROW, facing West.