

Inspection Photos
Location Name: LOEHR Larry R #1
Location ID: 322864



Photo 1 WH sign



Photo 2 PU

Inspection Photos
Location Name: LOEHR Larry R #1
Location ID: 322864



Colorado Oil and Gas Conservation Commission
40.0952, -104.78199, 1500.7m
Feb 26, 2019 1:47:15 PM

Photo 3 TNK BTRY



Colorado Oil and Gas Conservation Commission
40.09524, -104.78205, 1494.5m
Feb 26, 2019 1:47:40 PM

Photo 4 Stained soil appears to be from trucks off loading tanks

Inspection Photos
Location Name: LOEHR Larry R #1
Location ID: 322864



Photo 5 stained soil under load line to crude oil tank



**Photo 6 Stained soil under disconnected crude oil load line
and no bull plug on 2" VLV**

Inspection Photos
Location Name: LOEHR Larry R #1
Location ID: 322864



Photo 7 faded NPPA placard



Photo 8 stained soil 2" bull plug on crude oil load line to tank

Inspection Photos
Location Name: LOEHR Larry R #1
Location ID: 322864



Colorado Oil and Gas Conservation Commission
40.09492, -104.78185, 1487.3m
Feb 26, 2019 1:51:01 PM

Photo 9 stained soil around recirc pump



Colorado Oil and Gas Conservation Commission
40.09486, -104.78181, 1490.1m
Feb 26, 2019 1:51:32 PM

Photo 10 Separators and meter house

Inspection Photos
Location Name: LOEHR Larry R #1
Location ID: 322864



Photo 11 Stained soil inside separator house



Photo 12 no bull plug on drain line of separator

Inspection Photos
Location Name: LOEHR Larry R #1
Location ID: 322864



Photo 13 no bull plug on drain line of separator



Photo 14 Meter run