

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/26/2019

Submitted Date:

02/26/2019

Document Number:

696100305

FIELD INSPECTION FORM

Loc ID 330470 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspections@anadarko.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251358	WELL	PR	11/01/2018	GW	123-19161	HSR-ANDERSON 3-3	SI

General Comment:

This is a WELL Inspection.
Centralized Battery serves 2 Location ID's (330415, 330470).
Centralized Battery formerly served 1 additional Location ID (306134) (Well P&A).
Refer to FIR #696100303 and/or Location ID #330415 for Battery / Facility, Equipment info.
Well is SI.
Battery & ALL equipment is Shut-down.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:			Date:
Type	OTHER		
Comment:	Refer to FIR #696100303 and/or Location ID #330415 for additional Fencing info.		
Corrective Action:			Date:

Equipment:					corrective date
Type: Other	# 1				
Comment:	Bradenhead appears plumbed to surface.				
Corrective Action:				Date:	
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:				Date:	
Type:	#				
Comment:	Refer to FIR #696100303 and/or Location ID #330415 for additional Equipment info.				
Corrective Action:				Date:	

Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.432140,-104.883682	

Comment:	Centralized Battery serves 2 Location ID's (330415, 330470). Centralized Battery formerly served 1 additional Location ID (306134) (Well P&A). Refer to FIR #696100303 and/or Location ID #330415 for Tanks & Berms info.		
Corrective Action:		Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 251358 Type: WELL API Number: 123-19161 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI. Production valves closed & locked at well.
COGCC records indicate SI since 12/2018.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100306	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4746100