

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/26/2019

Submitted Date:

02/26/2019

Document Number:

696100307**FIELD INSPECTION FORM**

Loc ID 306134 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspections@anadarko.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285744	WELL	SI	05/01/2017	OW	123-24030	SHUR VIEW 18-3	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL** Inspection.
 Centralized Battery formerly served 1 Location ID (306134) (This well P&A).
 Centralized Battery serves 2 additional Location ID's (330415, 330470). (2-SI wells).
 P&A activity very recent. Reclamation in process.
 Wellhead has not been cut / capped. Has casing head attached w/ heavy temporary cap for safety.

Inspected Facilities									
Facility ID:	285744	Type:	WELL	API Number:	123-24030	Status:	SI	Insp. Status:	PA
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
<u>Comment:</u> <div>Appears to Plugged & Abandoned (P&A). Observed casing head only at wellsite. Form 42 #401919875 indicates plugging notice commence date: 01/30/2019.</div>									
Corrective Action: <div></div> Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
This well appears to have been recently P&A'd. Reclamation appears to be in process. Tank battery remains intact serving 2 other SI wells. The separator that this well had been connected to appears to be in process of being removed from battery.	evinsb	02/26/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100308	Site photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4746101