

Inspection Photos
Location Name: LORENCITO 1-17
API #: 05-071-06642
Insp. Doc. # 695100225



Colorado Oil & Gas Conservation Commission
37.0909, -104.79837, 2151.0m, 133°
2019/02/27 12:06:26



Colorado Oil & Gas Conservation Commission
37.09067, -104.79819, 2159.0m, 163°
2019/02/27 12:07:10

PHOTO 1: LOCATION

PHOTO 2: WELL SIGN/METER HOUSE

Inspection Photos
Location Name: LORENCITO 1-17
API #: 05-071-06642
Insp. Doc. # 695100225



PHOTO 3: VALVE MISSING.

PHOTO 4: HALF OF VALVE ON GROUND UNDER TBG LINE SEPARATION.

Inspection Photos

Location Name: LORENCITO 1-17

API #: 05-071-06642

Insp. Doc. # 695100225



PHOTO 5: WET SOIL OUTSIDE METER HOUSE. IT APPEARS THAT FLUID FROM SEPARATOR IS BEING DRAINED ON THE GROUND.

PHOTO 6: MORE WET SOIL OUTSIDE METER HOUSE. IT APPEARS THAT FLUID FROM SEPARATOR IS BEING DRAINED ON THE GROUND.

