

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	LOCATION SIGN		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	OTHER		
Comment:	THE TBG FLOWLINE IS SEPARATED NEAR WELLHEAD. IT APPEARS THAT THE VALVE BROKE. THERE IS A VALVE LYING ON THE GROUND NEAR WELLHEAD THAT IS BROKE IN HALF. SEE LOCATION PHOTOS.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	03/27/2019
Type	OTHER		
Comment:	WET SOIL OUTSIDE METER HOUSE. IT APPEARS THAT FLUID FROM SEPARATOR IS BEING DRAINED ON THE GROUND.		
Corrective Action:	Comply with Rule 603.f .	Date:	03/27/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	
Gas Meter Run	# 1		
Comment:	LAST CAL. 10/22/19		
Corrective Action:		Date:	
Other	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 217863 Type: WELL API Number: 071-06642 Status: PR Insp. Status: PR

Producing Well

Comment:			
Corrective Action:			Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695100226	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4747473