

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/21/2019

Submitted Date:

02/21/2019

Document Number:

689303319**FIELD INSPECTION FORM**

Loc ID 335058	Inspector Name: Holtz, Darin	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 22 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
Rider, Lindsay	970-285-2711	cogcc.inspections@caerusoila ndgas.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263197	WELL	PR	09/26/2002	GW	045-08105	ALP 24-16B1 (J24NW)	PR
263198	WELL	PR	07/12/2012	GW	045-08106	GMU 24-15B1(J24NW)	PR
263199	WELL	PR	09/24/2002	GW	045-08107	GMU 24-10A1(J24NW)	PR
263200	WELL	PR	09/13/2012	GW	045-08108	ALP 24-9B1(J24NW)	PR
271505	WELL	PR	09/13/2012	GW	045-09895	ALP 24-1C(J24NW)	PR
271506	WELL	PR	06/09/2004	GW	045-09894	ALP 24-5A(J24NW)	PR
430873	WELL	PR	02/04/2014	GW	045-21801	Alp Federal 24-12AA (J24NW)	PR
430874	WELL	PR	02/04/2014	GW	045-21802	Alp Fee 24-6AA (J24NW)	PR
430875	WELL	PR	01/14/2014	GW	045-21803	ALP Fee 24-3D (J24NW)	PR
430876	WELL	PR	01/12/2014	GW	045-21804	ALP FEE 24-3A (J24NW)	PR
430877	WELL	PR	10/01/2017	GW	045-21805	ALP Fee 24-6A (J24NW)	PR
430878	WELL	PR	05/08/2013	OW	045-21806	ALP Fee 24-5D (J24NW)	PR
430879	WELL	PR	01/11/2014	GW	045-21807	ALP FEE 24-2C (J24NW)	PR
430880	WELL	PR	01/05/2014	GW	045-21808	ALP Fee 24-12A (J24NW)	PR
430881	WELL	PR	02/04/2014	GW	045-21809	ALP Fee 24-6B (J24NW)	PR
430882	WELL	SI	11/01/2017	GW	045-21810	ALP FEE 24-12D (J24NW)	PR

**General Comment:**[Routine Field Inspection.](#)

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Emergency Contact Number:				
Comment:	1-800-791-7691			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	DEBRIS			
Comment:				
Corrective Action:				Date:
Type	TRASH			
Comment:				
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Equipment:</b>				
Type: Ancillary equipment	# 2			corrective date
Comment:	1 Chemical unit wellhead. 1 chemical unit at meter run.			
Corrective Action:				Date:
Type: Vertical Heated Separator	# 16			
Comment:	Mechanical condition of 24-12AA separator flow lines on top, and Gas out line on same unit, see photos.			
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.			Date: 03/22/2019
Type: Plunger Lift	# 16			
Comment:				
Corrective Action:				Date:
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date:

Type: VRT	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Vertical blowdown unit.		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	500 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)	Methanol tank	
Other (Capacity)	1000 gallon	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	263197	Type:	WELL	API Number:	045-08105	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	263198	Type:	WELL	API Number:	045-08106	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	263199	Type:	WELL	API Number:	045-08107	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	263200	Type:	WELL	API Number:	045-08108	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	271505	Type:	WELL	API Number:	045-09895	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	271506	Type:	WELL	API Number:	045-09894	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	430873	Type:	WELL	API Number:	045-21801	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	430874	Type:	WELL	API Number:	045-21802	Status:	PR	Insp. Status:	PR

<u>Producing Well</u>				
Comment:	Well Producing on plunger lift.			
Corrective Action:		Date:		
Facility ID:	430875	Type:	WELL	API Number: 045-21803 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Well Producing on plunger lift.			
Corrective Action:		Date:		
Facility ID:	430876	Type:	WELL	API Number: 045-21804 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Well Producing on plunger lift.			
Corrective Action:		Date:		
Facility ID:	430877	Type:	WELL	API Number: 045-21805 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Well Producing on plunger lift.			
Corrective Action:		Date:		
Facility ID:	430878	Type:	WELL	API Number: 045-21806 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Well Producing on plunger lift.			
Corrective Action:		Date:		
Facility ID:	430879	Type:	WELL	API Number: 045-21807 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Well Producing on plunger lift.			
Corrective Action:		Date:		
Facility ID:	430880	Type:	WELL	API Number: 045-21808 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Well Producing on plunger lift.			
Corrective Action:		Date:		
Facility ID:	430881	Type:	WELL	API Number: 045-21809 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Well Producing on plunger lift.			

Corrective Action:		Date:	
Facility ID: 430882    Type: WELL    API Number: 045-21810    Status: SI    Insp. Status: PR			
Producing Well			
Comment:	Well Producing on plunger lift.		
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
		Culverts				
Seeding						
		Gravel				
Slope Roughening						
Berms						
Ditches						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401947524	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4741991">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4741991</a>
689303320	Inspection photo 689303320	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4741987">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4741987</a>