

# Inspection Photos

API: 05-071-08776

Operator: XTO ENERGY INC

Inspection Date: 2/8/2019

## Inspection Photos



**Photo 1.** Access road remains to the location.



## Inspection Photos



**Photo 2.** Facing northwest along the access road.



## Inspection Photos



**Photo 3.** There are signs of erosion occurring along areas of the access road.



## Inspection Photos



**Photo 4.** Erosion is occurring on the side of the road and there are no BMP's.



## Inspection Photos



**Photo 5.** This water bar is filled in with sediment and stormwater is directed back toward the road.



## Inspection Photos



**Photo 6.** Further along the road near the location. There is erosion rills developed along the road.



## Inspection Photos



**Photo 7.** Facing northwest toward the location. Vegetation has not established the eastern side of the location.



## Inspection Photos



**Photo 8.** Facing northeast at the location. It appears there is a road that continues past the location.