

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/28/2019

Submitted Date:

02/28/2019

Document Number:

696100324**FIELD INSPECTION FORM**Loc ID 414444 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1001 17TH STREET #2000City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Oakman, Kari		kari.oakman@state.co.us	
,		cogccinspections@gwogco.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
414448	WELL	PR	11/01/2018	OW	123-30748	GREAT WESTERN 35-52	SI
446333	TANK BATTERY	AC	06/24/2016		-	GREAT WESTERN 35-52	AC

General Comment:

This is a WELL & BATTERY Inspection.
Well is SI.
Battery & ALL equipment is Shut-down.
Follow-up to FIR #689500912 dated 01/10/2019.
1 of 1 Corrective Action items appear addressed.
1.) Stained soil appears mitigated in noted areas from previous FIR. Refer to attached photos #3-12.
No Corrective Action items identified on this FIR.

Location				
Lease Road:				
Type	Access			
comment:	Adequate. Ruts appear to have been mitigated. See photos #15-16.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	Contents & Capacity labels on Crude oil tank & produced H2O vault are legible. They appear to be fading. Consider new labels.			
Corrective Action:				Date:
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	OTHER			
Comment:	Small localized areas of stained soil at multiple locations appear to be mitigated. See photos #3-12.			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Iron panel			
Corrective Action:				Date:
Type	SEPARATOR			
Comment:	Surrounded by metal berms.			
Corrective Action:				Date:
Type	IGNITOR/COMBUSTOR			
Comment:	Iron panel			
Corrective Action:				Date:

Equipment:				corrective date
Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:				Date:
Type: Other	# 1			
Comment:	Bradenhead appears plumbed to surface.			
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	ECD scrubber.			
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 2			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:				Date:
Type: Emission Control Device	# 1			
Comment:	Controls crude oil tank VOCs. Pilot: OFF Shut-down.			
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,
Comment:	Hatch on produced water tank now closed. See photos #13-14.				
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Shares berms w/ crude oil tank.				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.447264,-104.865073

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Shares berms w/ produced H2O vault.			
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 414448 Type: WELL API Number: 123-30748 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDSComment: SI. Observed production valves closed at well & separator.Corrective Action: Date: Facility ID: 446333 Type: TANK API Number: - Status: AC Insp. Status: AC

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100326	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4748293