

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/28/2019

Submitted Date:

02/28/2019

Document Number:

695100244

FIELD INSPECTION FORM

Loc ID 307941 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 1001 17TH STREET #1000
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Sutphin, Dirk		dirk.sutphin@state.co.us	
Amato, Joseph	719-845-2110/719-859-2263	josephamato@tcenergy.us	All Inspections
Santistevan, Vince	719-845-2102/719-680-9705	vincasantistevan@tcenergy.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259795	WELL	PR	09/12/2006	GW	071-07280	HILL RANCH 25-12V	PR

General Comment:

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	LOCATION SIGN		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	UNUSED EQUIPMENT ON LOCATION. SEE LOCATION PHOTOS.		
Corrective Action:	Comply with Rule 603.f .	Date:	03/28/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Ancillary equipment	# 1	corrective date	
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	BREADENHEAD IS PLUMBED TO SURFACE		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	LAST CAL. 1/9/19		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	TUBING HEAD IS NOT INSTALLED CORRECTLY. PRESSURE IS ESCAPING FROM TUBING HEAD. AND IT APPEARS THAT A RATCHET SPRAP IS BEING USED TO SECURE TUBING. 48 HOURS TO STOP LEAK.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	03/02/2019
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
Flaring:			

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 259795 Type: WELL API Number: 071-07280 Status: PR Insp. Status: PR

Producing Well

Comment:			
Corrective Action:			Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695100245	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4748445
695100246	VIDEO OF GAS LEAK	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4748446