

**Inspection Photo (s)**  
**Epperly 14A**  
**API #05-045-10464**  
**FIR Inspection # 689303392**



**Location Photo #1**



**Location Photo #2**

**Inspection Photo (s)**  
**Epperly 14A**  
**API #05-045-10464**  
**FIR Inspection # 689303392**



**Location Photo #3**



**Location Photo #4, 2 leaking fittings on inlets to separator.**



**Inspection Photo (s)**  
**Epperly 14A**  
**API #05-045-10464**  
**FIR Inspection # 689303392**



**Location Photo #5, leaking fitting on inlet flow line.**



**Location Photo #6, leaking fitting on inlet flow line.**