

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/27/2019

Submitted Date:

02/28/2019

Document Number:

692601497

FIELD INSPECTION FORM

Loc ID 320992 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10626
Name of Operator: DOVER ATWOOD CORPORATION
Address: 1875 HARSH AVENUE SE
City: MASSILLON State: OH Zip: 44646

Findings:

- 13 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Levengood, John	(330) 809-0630	jlevengood07@gmail.com	BACA Inspections
Crane, Rocky	(719) 529-0682	rockycrane@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205707	WELL	PR	01/01/2017	GW	009-06118	HUME 1	PR

General Comment:

[Routine Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Dirt road through farm ground		
Corrective Action	L		Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Inadequate sign, broke in half and does not display current operator.		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 02/07/2018
Type	TANK LABELS/PLACARDS		
Comment:	No tank labeling		
Corrective Action:	Install sign to comply with Rule 210.d		Date: 02/07/2018

Emergency Contact Number:			
Comment:	Lease sign does not display current emergency contact numbers		
Corrective Action:	Install sign to comply with Rule 210.b		Date: 01/07/2018

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds covering road and around some equipment.		
Corrective Action:	Comply with Rule 603.f		Date: 12/18/2017
Type	UNUSED EQUIPMENT		
Comment:	Unused pumping unit and horizontal separator on edge of location		
Corrective Action:	Comply with Rule 603.f		Date: 03/07/2018

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No
 Comment:
 Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Pipe fence around meter shed		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Wire panels around unit and wellhead		
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		37.243130,-102.178180

Comment:	Fiberglass open top water tank	Date:	
Corrective Action:		Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)	210bbbs	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Inadequate berms around tank			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).			Date: 01/07/2018

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 205707 Type: WELL API Number: 009-06118 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Not flowing at time of inspection](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
692601505	Location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4749613