

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/28/2019

Submitted Date:

02/28/2019

Document Number:

696100333

FIELD INSPECTION FORM

Loc ID 322743 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 19 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@nblenergy.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244187	WELL	TA	06/01/2017	OW	123-11980	STATE 7-36	TA
447544	TANK BATTERY	AC	09/02/2016		-	STATE-66N67W 36SENW	AC

General Comment:

This is a WELL & BATTERY Inspection.
Well is SI.
Battery & ALL equipment is Shut-down.
Centralized Battery serves 5 Location IDs (322743, 305621, 305622, 322742, 322744).
Follow-up to FIR #689300602 dated 01/04/2018.
2 of 2 Corrective Actions appear to have been addressed.
1.) Unused Equipment - Disconnected Gas meter run & unmarked gas meter run riser have been removed from site. See attached photos #4-6.
2.) Stained soil at wellhead appears remediated. See attached photos #7-8.
2 - NEW Corrective Actions identified on this FIR.
1.) Unused Equipment at wellsite & Gas meter run. Refer to Rule 603.f for guidance. See attached photos #2-3. (30 Days).
2.) SI/TA well per Alternative Mechanical Integrity Assurance Program. Doc #02385001 . Orange decommission tag for SI/TA status not present.

Location			
Lease Road:			
	Type	Access	
	comment:	Adequate	
	Corrective Action:		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
	Type	TANK LABELS/PLACARDS	
	Comment:		
	Corrective Action:		Date:
	Type	BATTERY	
	Comment:		
	Corrective Action:		Date:
	Type	WELLHEAD	
	Comment:	SI/TA well per Alternative Mechanical Integrity Assurance Program. Doc #02385001. Orange decommission tag for SI/TA status not present.	
	Corrective Action:	Install orange decommission tag to comply with Doc #02385001.	Date:
Emergency Contact Number:			
	Comment:	<input style="width: 50%;" type="text"/>	
	Corrective Action:	<input style="width: 50%;" type="text"/>	Date: _____
Good Housekeeping:			
	Type	UNUSED EQUIPMENT	
	Comment:	Unused Equipment at wellsite & Gas meter run. Refer to Rule 603.f for guidance. See attached photos #2-3. (30 Days).	
	Corrective Action:	Remove unused equipment at wellsite & Gas meter run. Comply w/ Rule 603.f.	Date: <u>04/01/2019</u>
	Type	UNUSED EQUIPMENT	
	Comment:	Disconnected Gas meter run & unmarked gas meter run riser have been removed from site. See attached photos #4-6.	
	Corrective Action:		Date:
	Type	OTHER	
	Comment:	Stained soil at wellhead appears remediated. See attached photos #7-8.	
	Corrective Action:		Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
	Comment:	<input style="width: 80%;" type="text"/>	
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
	Type	SEPARATOR	

Comment:	Barbed wire. Surrounded by metal berms.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbed wire.		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Barbed wire.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Bradenhead appears plumbed to surface.		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:	Controls crude oil tanks VOCs. Pilot: OFF Shut-down.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	ECD scrubber		
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,

Comment:		Centralized Battery serves 5 Location IDs (322743, 305621, 305622, 322742, 322744).				
Corrective Action:					Date:	
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		40.444231,-104.845074	
Comment:						
Corrective Action:					Date:	
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:		Shares berms w/ produced H2O vault.				
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	CONCRETE SUMP/VAULT		,	
Comment:						
Corrective Action:					Date:	
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity)	60 Bbls.					
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:		Shares berms w/ crude oil tank.				
Corrective Action:					Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 244187 Type: WELL API Number: 123-11980 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA. Well is disconnected from flowline.
COGCC records indicate SI since 12/2016.
Orange tag for SI/TA status NOT present.
Well is on Alternative Mechanical Integrity Assurance Program, Decommissioned
exemption list, see Doc #02385001 (NOBLE)

Corrective Action: _____ Date: _____

Facility ID: 447544 Type: TANK API Number: - Status: AC Insp. Status: AC

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass					
Gravel	Pass	Gravel	Pass			
Other	Pass					

Comment: [Portable concrete barriers around pig station and ECD line supports.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100334	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4749765