

Inspection Photo (s)
Wilson 43A-23
API #05-045-10441
FIR Inspection # 689303400



Location Photo #1



Location Photo #2

Inspection Photo (s)
Wilson 43A-23
API #05-045-10441
FIR Inspection # 689303400



Location Photo #3, 2 unmarked/unused flowline risers in tank battery.



Location Photo #4, 2 unmarked/unused flowline risers in tank battery.

Inspection Photo (s)
Wilson 43A-23
API #05-045-10441
FIR Inspection # 689303400



**Location Photo #5, 1 unmarked/unused
flowline risers in tank battery.**