

Inspection Photo (s)
Kaufman 23C-24
API #05-045-19649
FIR Inspection # 689303406



Location Photo #1



Location Photo #2

Inspection Photo (s)
Kaufman 23C-24
API #05-045-19649
FIR Inspection # 689303406



Location Photo #3



Location Photo #4

Inspection Photo (s)
Kaufman 23C-24
API #05-045-19649
FIR Inspection # 689303406



Location Photo #5, Temporary compressor for gas lift operation.



Location Photo #6, Stained ground underneath scrubber pot.

Inspection Photo (s)
Kaufman 23C-24
API #05-045-19649
FIR Inspection # 689303406



Location Photo #7, Stained ground underneath scrubber pot.



Location Photo #8, Stained ground underneath scrubber pot.

Inspection Photo (s)
Kaufman 23C-24
API #05-045-19649
FIR Inspection # 689303406



Location Photo #9, 2 Leaking fittings on unit 23A.



Location Photo #10, 1 of 2 Leaking fitting on unit 23A.

Inspection Photo (s)
Kaufman 23C-24
API #05-045-19649
FIR Inspection # 689303406



**Location Photo #11, 2 of 2 Leaking fitting on
unit 23A.**

Inspection Photo (s)
Kaufman 23C-24
API #05-045-19649
FIR Inspection # 689303406



Location Photo #12, Leaking fitting on unit 24D.



Location Photo #13, leaking fitting on 24D.