

**Inspection Photo (s)**  
**Kaufman 22D-24**  
**API #05-045-19909**  
**FIR Inspection # 689303408**



**Location Photo #1**



**Location Photo #2**

**Inspection Photo (s)**  
**Kaufman 22D-24**  
**API #05-045-19909**  
**FIR Inspection # 689303408**



**Location Photo #3**



**Inspection Photo (s)**  
**Kaufman 22D-24**  
**API #05-045-19909**  
**FIR Inspection # 689303408**



**Location Photo #4, stained ground at vent pipe for circulation pump.**



**Location Photo #5, stained ground at vent pipe for circulation pump.**

**Inspection Photo (s)**  
**Kaufman 22D-24**  
**API #05-045-19909**  
**FIR Inspection # 689303408**



**Location Photo #6, Leaking fitting on unit 21B.**



**Location Photo #7, Leaking fitting on unit 21B.**



**Inspection Photo (s)**  
**Kaufman 22D-24**  
**API #05-045-19909**  
**FIR Inspection # 689303408**



**Location Photo #8, Leaking fitting on unit 22B.**



**Location Photo #9, Leaking fitting on unit 22B.**

**Inspection Photo (s)**  
**Kaufman 22D-24**  
**API #05-045-19909**  
**FIR Inspection # 689303408**



**Location Photo #10, Leaking fitting on unit 31C.**



**Location Photo #11, Leaking fitting on unit 31C.**