

# Construction and Stormwater Inspection

February 21, 2019

Operator: ENERPLUS RESOURCES (USA) CORPORATION - #10177

Location ID: 455319

Inspection Document #: 682404572

Weld County, CO

SESE Section 20 T8N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Alberta Cities East Pad  
Location ID: 455319



**Photo 1.** Photo taken from the entrance of location, facing North. Photo illustrates a tracking device BMP that appears to be in proper function condition and the outer perimeter of the access road has seeded and straw crimped with mulch.



**Photo 2.** Photo taken from the southern location, facing West. Photo illustrates the cut slope has been temporarily stabilized with equipment tracking and hydromulch.

Inspection Photos  
Location Name: Alberta Cities East Pad  
Location ID: 455319



**Photo 3.** Photo taken from the southwestern perimeter of the location, facing West. Photo illustrates the western fill slope area has been seeded and straw crimped with mulch. The sediment trap is only for any runoff from the western fill slope area which includes the topsoil stockpile.



**Photo 4.** Photo taken from the southwestern well pad, facing North. Photo illustrates the ditch and berm has been temporarily stabilized with hydromulch. Also, photo illustrates the topsoil stockpile has been temporarily stabilized with equipment tracking, seeded and straw crimped with mulch.



Inspection Photos  
Location Name: Alberta Cities East Pad  
Location ID: 455319



**Photo 5.** Photo taken from the northern well pad, facing West. See comments under Photo 4.



**Photo 6.** Photo taken from the northeastern perimeter of location, facing South. Photo illustrates the Operator performed the previous corrective action to properly install the straw wattle BMP.

Inspection Photos  
Location Name: Alberta Cities East Pad  
Location ID: 455319



**Photo 7.** Photo taken from the northeastern perimeter of location, facing West. See comments under Photo 6.



**Photo 8.** Photo taken from the northeastern well pad, facing South. See comments under Photo 4.