

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/04/2019

Submitted Date:

03/04/2019

Document Number:

689303422

**FIELD INSPECTION FORM**

Loc ID 334952 Inspector Name: Holtz, Darin On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

12 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Rider, Lindsay	970-285-2711	cogcc.inspections@caerusoila ndgas.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268222	WELL	PR	11/29/2004	GW	045-09246	HMU 10-4D(F10)	PR
268224	WELL	PR	05/28/2004	GW	045-09247	HMU 10-3D (F10W)	PR
268225	WELL	PR	01/07/2008	GW	045-09248	HMU 10-6D (F10W)	PR
268226	WELL	PR	11/29/2004	GW	045-09249	HMU 10-5D (F10W)	SI

**General Comment:**

[Routine Field Inspection.](#)  
[Location is snow covered.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access road is muddy and heavily rutted.		
Corrective Action:		Date:	

Overall Good:

<b>Emergency Contact Number:</b>			
Comment:	1-800-791-7691		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Panel gates.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

<b>Inspected Facilities</b>			
Facility ID: <u>268222</u>	Type: <u>WELL</u>	API Number: <u>045-09246</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment: <span style="color: blue;">Well Producing on plunger lift.</span>			
Corrective Action:		Date:	
Facility ID: <u>268224</u>	Type: <u>WELL</u>	API Number: <u>045-09247</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment: <span style="color: blue;">Well Producing on plunger lift.</span>			
Corrective Action:		Date:	
Facility ID: <u>268225</u>	Type: <u>WELL</u>	API Number: <u>045-09248</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment: <span style="color: blue;">Well Producing on plunger lift.</span>			
Corrective Action:		Date:	
Facility ID: <u>268226</u>	Type: <u>WELL</u>	API Number: <u>045-09249</u>	Status: <u>PR</u> Insp. Status: <u>SI</u>
<b>Idle Well</b>			
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned	Reminder: _____		
Comment: <span style="color: blue;">Plunger lift, well is shut in at time of inspection. Last production records posted Nov, 2018.</span>			
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				Road is soft and muddy.
Compaction						Location is soft and rutted.

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303423	Inspection photo 689303423	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4752422">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4752422</a>