

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/04/2019

Submitted Date:

03/04/2019

Document Number:

689303426**FIELD INSPECTION FORM**

Loc ID 334921 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|--------------|---|---------------------------------|
| Rider, Lindsay | 970-285-2711 | cogcc.inspections@caerusoila ndgas.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------|-------------|
| 264836 | WELL | PR | 08/06/2003 | GW | 045-08945 | HMU 10-1B (A10WB) | PR |
| 264838 | WELL | PR | 08/13/2003 | GW | 045-08948 | HMU 10-2B (A10WB) | PR |
| 264839 | WELL | PR | 08/15/2003 | GW | 045-08949 | HMU 10-2D (A10WB) | PR |
| 264877 | WELL | PR | 08/02/2003 | GW | 045-08954 | ROSE RANCH 10-8B (A10WB) | PR |
| 265104 | WELL | PR | 08/15/2003 | GW | 045-08946 | HMU 3-15D (A10WB) | PR |

General Comment:[Routine Field Inspection.](#)

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | L | Date: | |

Overall Good: ☒

Emergency Contact Number:

Comment: 1-800-791-7691

Corrective Action:

Date: _____

Overall Good: ☐

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--------------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Panel gates. | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Vertical Heated Separator | # 5 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 5 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | |
|--------------------|---|----------|-----------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CONDENSATE | 1 | 300 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

| Berms | | | | | | |
|--|---------------|---------------------|---------------------|-------------|--------|--|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| | | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | Date: | | |
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CONDENSATE | 2 | 500 BBLs | STEEL AST | | , | |
| Comment: 3 tanks in centralized battery. | | | | | | |
| Corrective Action: | | | | Date: | | |
| Paint | | | | | | |
| Condition | Adequate | | | | | |
| Other (Content) | Methanol tank | | | | | |
| Other (Capacity) | 1000 gallon | | | | | |
| Other (Type) | | | | | | |
| Berms | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | | |
| Comment: | | | | | | |
| Corrective Action: | | | | Date: | | |
| Venting: | | | | | | |
| Yes/No | NO | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |
| Flaring: | | | | | | |
| Type | | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |

| Inspected Facilities | | | | | | | | | |
|-----------------------|---------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 264836 | Type: | WELL | API Number: | 045-08945 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 264838 | Type: | WELL | API Number: | 045-08948 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 264839 | Type: | WELL | API Number: | 045-08949 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 264877 | Type: | WELL | API Number: | 045-08954 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 265104 | Type: | WELL | API Number: | 045-08946 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: [Location is snow covered.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------------|---|
| 689303427 | Inspection photo 689303427 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4752425 |