

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/05/2019

Submitted Date:

03/05/2019

Document Number:

687903780

FIELD INSPECTION FORM

Loc ID 325355 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
6 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 10663
 Name of Operator: ENDURING RESOURCES LLC
 Address: 1050 17TH STREET SUITE 2500
 City: DENVER State: CO Zip: 80265

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Walter, Kyle		kwalter@enduringresources.com	SW Inspection Reports
Labowskie, Steve		steve.labowskie@state.co.us	
McDaniel, James	505-444-3004	jmcdaniel@enduringresources.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
150332	UIC DISPOSAL	AC	06/01/1993		-	STATE 1-36	AC
214631	WELL	IJ	01/01/2017	DSPW	067-06235	STATE 1-36	IJ

General Comment:
[Bradenhead test conducted with Southwest FIU Supervisor Steve Labowskie. Downloadable photos at end of inspection report.](#)

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Old operator name on tank labels. Missing NFPA diamond labels on 400 BBL tanks.		
Corrective Action:	Comply with Rule 210	Date:	04/05/2019

Emergency Contact Number:

Comment:	Correct Contact information.	Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 150332 Type: UIC API Number: - Status: AC Insp. Status: AC

BradenHead

Comment: There was .3 PSI on bradenhead at start of test with no blowdown when gauge was removed. No changes on tubing and casing during blowdown and no instaneous pressure.

Corrective Action:

Date:

Facility ID: 214631 Type: WELL API Number: 067-06235 Status: IJ Insp. Status: IJ

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687903781	Missing Tank Labeling	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4753332