

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/04/2019

Submitted Date:

03/04/2019

Document Number:

685100602

**FIELD INSPECTION FORM**

Loc ID 318042 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@Anadarko.com	
Gomez, Jason		jason.gomez@state.co.us	

**General Comment:**

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	TRASH		
Comment:	55 Gallon drum on location by wellhead.		
Corrective Action:	Comply with Rule 603.f .		Date: 03/14/2019
Type	UNUSED EQUIPMENT		
Comment:	Horses Head next to wellhead.		
Corrective Action:	Comply with Rule 603.f .		Date: 06/04/2019
Type	OTHER		
Comment:	Gas leak found on motor valve used for plunger lift equipment.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 06/04/2019
Type	UNUSED EQUIPMENT		
Comment:	Metal containment next to wellhead not in use.		
Corrective Action:	Comply with Rule 603.f .		Date: 04/04/2019
Type	UNUSED EQUIPMENT		
Comment:	Pump jack on location while well is produced by plunger lift equipment.		
Corrective Action:	Comply with Rule 603.f .		Date: 06/04/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**COGCC Comments**

Comment	User	Date
At time of inspection on the Frazier Jon Gu #1 at approx. 1222 a leak from a motor valve was found on the wellhead. Called the emergency # on wellhead and got a hold of a company representative. Representative sent out pumper to address the gas leak. Pumper arrived, and shut valve to stop leak. Unused pumpjack on location with plunger lift equipment installed on wellhead. Informed the pumper about the CA that will need to be addressed. Inspected rest of location.	medinaj	03/04/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100603	Location Pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4754512">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4754512</a>