

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2019

Submitted Date:

03/06/2019

Document Number:

685100625

**FIELD INSPECTION FORM**Loc ID 336147 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections
Gomez, Jason		jason.gomez@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244830	WELL	SI	08/01/2018	GW	123-12625	CHAMPLIN 86 AMOCO 0 8	SI
299656	WELL	SI	05/01/2017	OW	123-29457	SEC FOUR 14-4	SI
299657	WELL	SI	05/01/2017	OW	123-29458	SEC FOUR 13-4	SI
299658	WELL	SI	05/01/2017	OW	123-29459	SEC FOUR 12-4	SI
299660	WELL	SI	05/01/2017	GW	123-29461	SEC FOUR 22-4	SI
299661	WELL	PA	07/09/2018	GW	123-29462	SEC FOUR 33-4	PA
299662	WELL	SI	05/01/2017	OW	123-29463	SEC FOUR 32-4	SI
299663	WELL	SI	05/01/2017	GW	123-29464	SEC FOUR 35-4	SI

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Pump Jack

# 0

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No

NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: <u>244830</u>	Type: <u>WELL</u>	API Number: <u>123-12625</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>299656</u>	Type: <u>WELL</u>	API Number: <u>123-29457</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>299657</u>	Type: <u>WELL</u>	API Number: <u>123-29458</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>299658</u>	Type: <u>WELL</u>	API Number: <u>123-29459</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>299660</u>	Type: <u>WELL</u>	API Number: <u>123-29461</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>299661</u>	Type: <u>WELL</u>	API Number: <u>123-29462</u>	Status: <u>PA</u>	Insp. Status: <u>PA</u>
Facility ID: <u>299662</u>	Type: <u>WELL</u>	API Number: <u>123-29463</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>299663</u>	Type: <u>WELL</u>	API Number: <u>123-29464</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>

**Workover**Comment: P&A on Sec Four 22-4Corrective Action: Date: **COGCC Comments**

Comment	User	Date
Arrived on location at approx. 1150, March 6, 2019. Inspected wellsite. During time of inspection work-over rig is using fishing spear to POOH 4.5 11.6 PPF Production casing, cut at approx 1060' MD. N/U 4.5" BOP, and preparing to cement to surface. While on location appears that site is in compliance of COGCC rules.	medinaj	03/06/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100626	Location Pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4754524">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4754524</a>