

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/27/2019

Submitted Date:

03/06/2019

Document Number:

689802379**FIELD INSPECTION FORM**

Loc ID 313018	Inspector Name: Waldron, Emily	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 3 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>10550</u> Name of Operator: <u>MUSTANG RESOURCES LLC</u> Address: <u>1660 LINCOLN STREET SUITE 1450</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80264</u>				
ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE				

Contact Information:			
Contact Name	Phone	Email	Comment
Couts, Brandon		bcoutts@mustangresourcesllc.com	Field Operations
Smith, Matt		msmith@mustangresourcesllc.com	

General Comment:
Routine FIU inspection. Road not plowed when inspector attempted inspection. Evidence of previous plowing. Follow-up inspection will be performed after snowmelt.

COGCC Comments		
Comment	User	Date
Routine FIU inspection. Road not plowed when inspector attempted inspection. Evidence of previous plowing. Follow-up inspection will be performed after snowmelt.	waldrone	03/06/2019

Attached Documents		
You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:		
Document Num	Description	URL
689802380	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4754789