

Inspection Photos
Location Name: SUNSET 24-3
API #: 05-071-08158
Insp. Doc. # 695100269



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN/METER HOUSE

Inspection Photos
Location Name: SUNSET 24-3
API #: 05-071-08158
Insp. Doc. # 695100269



**PHOTO 3: MECHANICAL CONDITION/ APPEARS PUMPJACK
MOTOR IS LEAKING OIL**



**PHOTO 4: IMPACTED SOIL/ OIL APPEARS TO BE LEAKING FROM
PUMPJACK MOTOR AND RUNNING ONTO THE GROUND ON
SOUTHWEST SIDE OF PUMPJACK**