

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/06/2019

Submitted Date:

03/06/2019

Document Number:

695100271

**FIELD INSPECTION FORM**

Loc ID 307564 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1801 BROADWAY SUITE 350

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217836	WELL	PR	10/26/2003	GW	071-06615	TAMBURELLI 33-3	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	LOCATION SIGN EMERGENCY NUMBER THAT IS POSTED IS NOT ACCURATE.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	04/06/2019

Emergency Contact Number:		
Comment:		
Corrective Action:		Date: _____

<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:	TRASH & DEBREE INSIDE PRIME MOVER HOUSE		
Corrective Action:	Comply with Rule 603.f .	Date:	03/18/2019
Type	OTHER		
Comment:	PRODUCED WATER DRIPPING FROM SEPARATOR TO THE GROUND		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	04/06/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:	CALIBRATION REPORT IS PAST DUE/ OVER ONE YEAR SINCE LAST CALIBRATION.		
Corrective Action:	Measure gas per Rule 329.	Date:	04/06/2019
Type: Compressor	# 0		
Comment:			
Corrective Action:		Date:	
Type: Other	#		
Comment:	BREADENHEAD IS PLUMBED TO SURFACE		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	

<b><u>Venting:</u></b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<b><u>Flaring:</u></b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 217836 Type: WELL API Number: 071-06615 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695100272	LOCATION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4754816">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4754816</a>