

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/07/2019

Submitted Date:

03/07/2019

Document Number:

689303454

**FIELD INSPECTION FORM**

Loc ID 435118 Inspector Name: Holtz, Darin On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 15 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Rocky, TEP		COGCCInspectionReports@terraep.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435116	WELL	PR	12/16/2014	GW	045-22216	State of Colorado KP 421-9	PR
435117	WELL	PR	07/20/2017	GW	045-22217	State of Colorado KP 32-9	PR
435119	WELL	PR	12/16/2014	GW	045-22218	State of Colorado KP 431-9	PR
435120	WELL	PR	11/11/2014	GW	045-22219	State of Colorado KP 422-9	PR

**General Comment:**

[Routine Field Inspection.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Muddy and rutted near the top, requires 4x4 to access location.		
Corrective ActionL		Date:	

Overall Good:

<b>Emergency Contact Number:</b>			
Comment:	1-970-285-9377		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Debris on location, see photos.		
Corrective Action:	Comply with 603.f.	Date:	04/08/2019

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panel fence.		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Hog panel fence.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panel fence		
Corrective Action:		Date:	

<b>Equipment:</b>					corrective date
Type:	Plunger Lift	# 4			
Comment:					
Corrective Action:		Date:			
Type:	Ancillary equipment	# 1			
Comment:	Chemical unit at wellhead.				
Corrective Action:		Date:			
Type:	Pig Station	# 1			
Comment:					
Corrective Action:		Date:			

Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	HEATED STEEL AST		,
Comment:	4 tanks in a centralized containment.				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities			
Facility ID:	<u>435116</u>	Type:	<u>WELL</u>
API Number:	<u>045-22216</u>	Status:	<u>PR</u>
Insp. Status:	<u>PR</u>		
<b>Producing Well</b>			
Comment:	<u>Well Producing on plunger lift.</u>		
Corrective Action:		Date:	
Facility ID:	<u>435117</u>	Type:	<u>WELL</u>
API Number:	<u>045-22217</u>	Status:	<u>PR</u>
Insp. Status:	<u>PR</u>		
<b>Producing Well</b>			
Comment:	<u>Well Producing on plunger lift.</u>		
Corrective Action:		Date:	
Facility ID:	<u>435119</u>	Type:	<u>WELL</u>
API Number:	<u>045-22218</u>	Status:	<u>PR</u>
Insp. Status:	<u>PR</u>		
<b>Producing Well</b>			
Comment:	<u>Well Producing on plunger lift.</u>		
Corrective Action:		Date:	
Facility ID:	<u>435120</u>	Type:	<u>WELL</u>
API Number:	<u>045-22219</u>	Status:	<u>PR</u>
Insp. Status:	<u>PR</u>		
<b>Producing Well</b>			
Comment:	<u>Well Producing on plunger lift.</u>		
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303455	Inspection photo 689303455	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4754983">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4754983</a>