

Inspection Photos

API: 05-071-06636

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 3/1/2019

Inspection Photos



Photo 1. Erosion is occurring along the access road at Lat/Long:37.08649,-104.75026.

Inspection Photos



Photo 2. Stormwater appears to flow across the road causing significant erosion.

Inspection Photos



Photo 3. Stormwater is flowing toward the access road (red arrow) and not toward the culvert (yellow arrow). Culvert may be plugged up with debris.

Inspection Photos



Photo 4. Erosion is cutting into the road, approximately 8-10 ft. deep.

Inspection Photos



Photo 5. Well sign present at the location.

Inspection Photos



Photo 6. Facing toward the north side of the location. Vegetation is established and guy line marker is present.

Inspection Photos



Photo 7. Facing toward the south side of the location. Vegetation is established along the fill slope.

Inspection Photos



Photo 8. Culvert is filled in with sediment and stormwater is flowing across the road.
Lat/Long:37.09338,-104.74751