

# Inspection Photos

API: 05-071-08860

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 3/1/2019

## Inspection Photos



**Photo 1.** Facing south toward the recontoured and reclaimed location.

## Inspection Photos



**Photo 2.** Rock rip/rap is placed in the drainage channel.

## Inspection Photos



**Photo 3.** Facing back to the north at the location.

## Inspection Photos



**Photo 4.** Facing west toward the recontoured slope.

## Inspection Photos



**Photo 5.** Facing north at the location.