

Inspection Photos

API: 05-071-06671

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 3/1/2019

Inspection Photos



Photo 1. Erosion is occurring along the access road at Lat/Long:37.09966,-104.73441. Facing northwest.

Inspection Photos



Photo 2. Erosion is occurring along the access road. Facing southeast.

Inspection Photos



Photo 3. Facing southwest at Lat/Long:37.09966,-104.73441. The culvert is filled in with sediment and erosion is occurring down the road.

Inspection Photos



Photo 4. Further along the road traveling toward the top of the ridge near the [TAD POLE #21-12](#) location. Erosion is occurring down the road past the culvert.

Inspection Photos



Photo 5. Facing east toward the [TAD POLE #21-12](#) location.